

## 540008

### Installation of the Ford Speed Sensor Plug



1. Remove the retaining clip from the speed sensor which holds the speedometer cable in place. Pull out the speedometer cable and make sure the stock O-ring remains in place.

**NOTE:** without the O-ring in place, the sensor will leak.



2. Insert the sensor plug in place of the speedometer cable and re-insert the retaining clip to keep it in place.



3. 1983-95 Mustang: splice into the gray/black (VSS+) wire at the speed sensor; connect this to the speed input (SPD SND) terminal on your control box. Consult a wiring diagram specific to your model and trim level to locate the VSS + wire from the speed sensor.

**⚠WARNING:** This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)